

## Under Review Notification

**Raised By:** Ketan Tailor

**Product #:** RBE117-12020W16

**Date:** 06/14/2019

**Product Name:** Base Extractor Free Wheel

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBE117-12020W16-1	RBE117-12020W16 REV.	Y	N	N	Y	N	N	N	19-772	see below
RBE117-12020W16-3	RBE117-12020W16 REV.	Y	N	N	Y	N	N	N	19-772	see below

**Description of Issue:**

-1: 3D model was not correctly dimensioned. center to center dimension was 4.126, should be 4.158

-3: Surface finish was black anodized, should be black oxide

Orders can still be shipped with engineering sign off

Drawing will be updated

<b>Distribution:</b>	VP Operations Director of Operations Director Quality Assurance QC Coordinator	Director of Engineering Chief Engineer Engineering Project Managers Engineering Clerk	Customer Support Manager Production Engineers Production Planners Purchasing Manager	Technical Support Product Manager - Solutions Provider Supply Chain Director / Senior Buyer Marketing Eugene
----------------------	---	--	---	---